



Security Advisory 2023-001

As of: Sep 19, 2023



Important Information

System Solutions with MOVI-C® CONTROLLER
in Combination with CODESYS



Table of Contents

1 Security vulnerabilities in CODESYS products..... 4

1.1 Problem..... 4

1.2 Details 4

2 Affected products..... 6

2.1 Overview of affected products 6

2.2 Affected MAXOLUTION® system solutions 7

3 General corrective measures 8

3.1 Network security and access protection 8

3.2 Check the firmware version used..... 8

3.3 Access protection and user management..... 8

4 Product-specific information and measures 9

4.1 Components..... 9

4.2 Mobile assistance systems with VDA5050 interface..... 11

5 General information 13

5.1 Disclaimer 13

5.2 Product names and trademarks 13

5.3 Copyright notice 13

5.4 Document history 13

As of: Sep 19, 2023

1 Security vulnerabilities in CODESYS products

1.1 Problem

CODESYS GmbH has identified a number of weak points in CODESYS products and published corresponding advisories. Products and system solutions from SEW-EURODRIVE use CODESYS software components and are partially affected by these vulnerabilities.

SEW-EURODRIVE is currently examining with high priority to what extent our products, components, and systems are affected by these vulnerabilities. In the meantime, our customers should immediately ensure that they have implemented the best practices for cyber security in their areas to protect themselves from vulnerabilities. These include, for example, securing all systems with remote access using firewalls. Ensure that unauthorized access is prevented, particularly with Ethernet-based networked systems and engineering interfaces. Use IT-specific safety standards to complement access protection.

1.2 Details

The following table contains the relevant CODESYS Security Advisories. Further information on these vulnerabilities is available in English at the following link: [Security Reports \(codesys.com\)](https://www.codesys.com/Security-Reports). The owners of this website are responsible for the contents and the presentation of the topic.

| Advisory-Nummer | Advisory |
|-----------------|--|
| 2023-10 | CODESYS Security Advisory 2023-10 |
| 2023-09 | CODESYS Security Advisory 2023-09 |
| 2023-08 | CODESYS Development System V3 CODESYS Security Advisory 2023-08 |
| 2023-07 | CODESYS Development System V3 CODESYS Security Advisory 2023-07 |
| 2023-06 | CODESYS Development System V3 CODESYS Security Advisory 2023-06 |
| 2023-05 | CODESYS Control V3 CODESYS Security Advisory 2023-05 |
| 2023-04 | CODESYS Control V3 CODESYS Security Advisory 2023-04 |
| 2023-03 | Security update for CODESYS runtime system V3 communication server |
| 2023-02 | Security update for CODESYS Control V3 |
| 2023-01 | Security update for CODESYS Control V3 file access |
| 2022-16 | Security update for CODESYS Control V3 communication server |
| 2022-15 | Security update for CODESYS V3 boot application encryption |
| 2022-14 | Security update for CODESYS V3 Visualization |
| 2022-13 | Security update for CODESYS Gateway V2 |
| 2022-12 | Security update for CODESYS V2 password transport |
| 2022-11 | Security update for CODESYS Control V2 |
| 2022-10 | Security update for CODESYS OPC DA Server V3 |
| 2022-09 | Security update for CODESYS V3 products containing a CODESYS communication server |
| 2022-08 | Security Note: Framework for attacks on ICS and SCADA systems (INCONTROLLER / PIPEDREAM) |

| Advisory- Nummer | Advisory |
|---------------------|---|
| 2022-07 | Security update for CODESYS V3 web server |
| 2022-06 | Security update for several CODESYS V3 products containing a CODESYS communication server |
| 2022-05 | Security update for CODESYS Control V3 online user management |
| 2022-04 | Security update for various CODESYS V3 products using the CODESYS communication protocol |
| 2022-03 | Security update for SysDrv3S |
| 2022-02 | Security update for CODESYS Control V3 configuration file access |
| 2022-01 | Security update for CODESYS PROFINET |
| 2021-18 | Security update for CODESYS Git |
| 2021-15 | Security update for CODESYS V2 web server |
| 2021-13 | Security update for CODESYS Development System V3 including CODESYS Installer and CODESYS SVN |
| 2018-04 | Security update for CODESYS V2 and V3 runtime systems |

As of: Sep 19, 2023

2 Affected products

2.1 Overview of affected products

| CODESYS Advisory | Control cabinet controllers | | | | | Decentralized controllers | | Software ¹⁾ | | Mea- sure (→ 9) |
|---------------------|-----------------------------|--------|--------|--------|--------|------------------------------|--------|------------------------|------------|--------------------|
| | UHX25A | UHX45A | UHX65A | UHX85A | UHX86A | FHX25A | FHX45A | Visualization | IEC-Editor | |
| 2023-10 | – | – | – | – | – | – | – | x | x | M16 |
| 2023-09 | – | – | – | – | – | – | – | x | x | M15 |
| 2023-08 | x | x | x | x | x | x | x | x | x | M11 |
| 2023-07 | – | – | – | – | – | – | – | x | x | M12 |
| 2023-06 | – | – | – | – | – | – | – | x | x | M13 |
| 2023-05 | x | x | x | x | x | x | x | x | x | M11 |
| 2023-04 | x | x | x | x | x | x | x | x | x | M11 |
| 2023-03 | x | x | x | x | x | x | x | x | x | M12 |
| 2023-02 | x | x | x | x | x | x | x | x | x | M11 |
| 2023-01 | – | – | – | – | – | – | – | – | – | – |
| 2022-16 | x | x | x | x | x | x | x | x | – | M14 |
| 2022-15 | – | – | – | – | – | – | – | – | – | – |
| 2022-14 | x | x | x | – | – | x | x | x | x | M10 |
| 2022-13 | – | – | – | – | – | – | – | – | – | – |
| 2022-12 | x | x | x | x | x | x | x | x | – | M9 |
| 2022-11 | – | – | – | – | – | – | – | – | – | – |
| 2022-10 | – | – | – | – | – | – | – | – | – | M2 |
| 2022-09 | x | x | x | x | – | x | x | x | x | M7 |
| 2022-08 | x | x | x | x | x | x | x | x | – | M11 |
| 2022-07 | x | x | – | x | – | x | x | x | x | M8 |
| 2022-06 | x | x | x | x | – | x | x | x | x | M7 |
| 2022-05 | – | – | – | – | – | – | – | – | – | – |
| 2022-04 | x | x | x | x | – | x | x | x | x | M7 |
| 2022-03 | – | – | – | – | – | – | – | – | – | – |
| 2022-02 | x | x | x | x | – | x | x | x | x | M6 |
| 2022-01 | – | – | – | – | – | – | – | – | – | – |
| 2021-18 | – | – | – | – | – | – | – | – | – | M2 |
| 2021-15 | – | – | – | – | – | – | – | – | – | – |
| 2021-13 | x | x | x | x | – | x | x | x | x | M5 |

As of: Sep 19, 2023

31554008/EN – 09/2023

| CODESYS Advisory | Control cabinet controllers | | | | | Decentralized controllers | | Software ¹⁾ | | Mea- sure (→ 9) |
|---------------------|-----------------------------|--------|--------|--------|--------|------------------------------|--------|------------------------|------------|--------------------|
| | UHX25A | UHX45A | UHX65A | UHX85A | UHX86A | FHX25A | FHX45A | Visualization | IEC-Editor | |
| 2018-04 | x | x | – | x | – | – | – | – | x | M3 |

1) The IEC Editor is part of MOVISUITE® standard. You cannot download or install the IEC Editor individually. The IEC Editor is only available as part of MOVISUITE® standard. The IEC Editor is not included in MOVISUITE® compact.

2.2 Affected MAXOLUTION® system solutions

- All MAXOLUTION® AGV and mobile assistance systems with VDA5050 interface to the fleet controller also contain a CODESYS control. Depending on the delivery time and update status, the vehicles may be affected by the vulnerabilities listed in chapter "Details" (→ 4). Chapter "Mobile assistance systems with VDA5050 interface" (→ 11) provides detailed information and a recommendation for safe operation of the system solution.
- The stationary log controller "Operator terminal PA10005586 18.5 OEM" (part number 28274334) also has a CODESYS control section, which, however, cannot be accessed via a network interface accessible from outside if used according to the documentation. It is not possible to exploit existing weak points in the CODESYS SW components without further ado.
- The "AGV-Basic" automation package and the floor conveyor vehicles created with it and the associated logistics controller (LC) also use a CODESYS control, which, like all other components of the modular automation system, are sold as individual components. For existing CODESYS weak points of the MOVI-C® CONTROLLER, you must therefore proceed according to chapter "Overview of affected products" (→ 6) and the notes referenced therein in chapter "Product-specific information and measures" (→ 9).
- MOVIVISION® EMS and skilnet applications usually do not contain a CODESYS-based controller and are therefore not affected by the vulnerabilities mentioned in chapter "Details" (→ 4).

As of: Sep 19, 2023

3 General corrective measures

- Unused active network connections generally increase the security risk. Limit network access to the devices to minimize the risk of attacks.
- Unless absolutely necessary, devices/systems should be disconnected from the higher-level network.
- Prevent unauthorized people or devices from gaining access to affected devices and network segments in which affected devices are being operated.
- If you access the devices with a laptop, use a point-to-point Ethernet connection. The laptops should not be connected to the network.

3.1 Network security and access protection

A bus system can be used to adapt electronic drive components to the system conditions within a wide range. This entails the risk of a parameter change not being visible externally, resulting in unexpected – but not uncontrolled – system behavior, and this may impact negatively on operational safety and reliability, system availability or data security.

Ensure that unauthorized access is prevented, particularly with respect to Ethernet-based networked systems and engineering interfaces.

Use IT-specific safety standards to increase access protection to the ports. For a port overview, refer to the respective technical data of the device in use.

3.2 Check the firmware version used

The MOVISUITE® version, the firmware version of the MOVI-C® CONTROLLER and the MOVI-C® FIELD CONTROLLER must always be up to date. You can download the latest MOVISUITE® version free of charge from the SEW-EURODRIVE website. The latest MOVISUITE® version also includes the latest approved firmware versions of the MOVI-C® CONTROLLER and the MOVI-C® FIELD CONTROLLER. For a detailed description of the firmware update process, refer to the operating instructions of the corresponding product.

When starting up new systems, make sure that the latest firmware version is always used. Check the firmware version of the MOVI-C® CONTROLLER and the MOVI-C® FIELD CONTROLLER via MOVISUITE®. If the latest firmware version is not used, update the firmware version.

3.3 Access protection and user management

SEW-EURODRIVE recommends activating and permanently using user management and secure engineering from the security features as of MOVISUITE® version V2.40.

4 Product-specific information and measures

4.1 Components

| | |
|----|---|
| M2 | <p>Affected Codesys software components</p> <ul style="list-style-type: none"> For Advisory 2022-10: CODESYS OPC DA Server SL For Advisory 2021-18: CODESYS Git <p>The specified CODESYS software components are not included in the scope of delivery of SEW-EURODRIVE but can be installed as an optional package. In this case, please observe the information in the CODESYS advisory</p> |
| M3 | <p>This only affects the following components:</p> <ul style="list-style-type: none"> MOVI-C® CONTROLLER UHX25A, UHX45A with firmware < V02.00 MOVI-C® CONTROLLER UHX85A with firmware < V03.00 MOVISUITE® < V2.0.114.100 IEC-Editor < 3.5.12.3 <p>Check your version of MOVISUITE® and the firmware versions of the MOVI-C® CONTROLLER. Update them, if necessary.</p> |
| M5 | <p>Check your version of MOVISUITE®:</p> <ul style="list-style-type: none"> MOVISUITE® < V2.30: Update to MOVISUITE® V2.40 or later. MOVISUITE® V2.30: A manual update of the CODESYS installer to V1.3.0 is required from the CODESYS website. Alternatively, install MOVISUITE® V2.40 or later. |
| M6 | <p>This only affects the following components:</p> <ul style="list-style-type: none"> MOVI-C® CONTROLLER UHX25A, UHX45A, UHX65A, UHX85A with firmware < V08.00 MOVI-C® FIELD CONTROLLER FHX25A, FHX45A with firmware < V08.00 MOVISUITE® < V2.40 IEC-Editor < V3.5.18.20 Visualization < 1.4 <p>Steps for rectification:</p> <ul style="list-style-type: none"> Update MOVISUITE® to V2.40 or later. Update the MOVI-C® CONTROLLER firmware to V08.00 or later. Activate the security features that are available as of V2.40. If you are using the MOVIKIT® Visualization software module, update the IEC Editor to V3.5.18.20 or later and activate the security features. Set up the appropriate rights for accessing the file system in the "Access rights" tab of the MOVI-C® CONTROLLER in the IEC Editor. |

As of: Sep 19, 2023

| | |
|-----|--|
| M7 | <p>This only affects the following components:</p> <ul style="list-style-type: none"> • MOVI-C® CONTROLLER UHX25A, UHX45A, UHX65A, UHX85A with firmware < V08.00 • MOVI-C® FIELD CONTROLLER FHX25A, FHX45A with firmware < V08.00 • MOVISUITE® < V2.40 • IEC-Editor < V3.5.18.20 • Visualization < 1.4 <p>Steps for rectification:</p> <ul style="list-style-type: none"> • Update MOVISUITE® to V2.40 or later. • Update the MOVI-C® CONTROLLER firmware to V08.00 or later. • Activate the security features that are available as of V2.40. |
| M8 | <p>This only affects the following components:</p> <ul style="list-style-type: none"> • MOVI-C® CONTROLLER UHX25A, UHX45A, UHX85A with firmware < V08.00 • MOVI-C® FIELD CONTROLLER FHX25A, FHX45A with firmware < V08.00 • MOVISUITE® < V2.40 • IEC-Editor < V3.5.18.20 • Visualization < 1.4 <p>The threat exists when web visualization is activated on the MOVI-C® CONTROLLER and in the MOVIKIT® Visualization software module. If you do not need web visualization, please deactivate it.</p> <p>As an alternative, carry out the following steps:</p> <ul style="list-style-type: none"> • Update MOVISUITE® to V2.40 or later. • Update the MOVI-C® CONTROLLER firmware to V08.00 or later. • Activate the security features that are available as of V2.40. • Update the IEC Editor to V3.5.18.20 or later and activate the security features. |
| M9 | <p>The threat exists in the case of Generation B mixed operation with MOVI-C® CONTROLLER and MOVI-C® FIELD CONTROLLER or when using CODESYS V2.3 legacy products with MOVI-C® CONTROLLER. SEW-EURODRIVE recommends avoiding such mixed operations.</p> <p>If this is unavoidable, observe chapter "General corrective measures" to reduce the risks.</p> |
| M10 | <p>This only affects the following components:</p> <ul style="list-style-type: none"> • MOVI-C® CONTROLLER UHX25A, UHX45A, UHX65A with firmware < V08.00 • MOVI-C® FIELD CONTROLLER FHX25A, FHX45A with firmware < V08.00 • MOVISUITE® < V2.40 • IEC-Editor < V3.5.18.20 • Visualization < 1.4 <p>The threat exists when web visualization is activated on the MOVI-C® CONTROLLER and in the MOVIKIT® Visualization software module. If you do not need web visualization, please deactivate it.</p> <p>If you use MOVISUITE® V2.30 or V2.31 (IEC Editor 3.5.17.2, MOVI-C® CONTROLLER firmware V07.00 or V07.01), you can manually reinstall CODESYS Visualization V4.2.0.0 in the IEC Editor.</p> <p>As an alternative, carry out the following steps:</p> <ul style="list-style-type: none"> • Update MOVISUITE® to V2.40 or later. • Update the MOVI-C® CONTROLLER firmware to V08.00 or later. • Activate the security features that are available as of V2.40. • Update the IEC Editor to V3.5.18.20 or later and activate the security features. |

| | |
|-----|--|
| M11 | <p>Currently under review.</p> <p>To exploit this vulnerability, a successful login must take place on the affected product. User management with strong passwords and secure engineering, which are available as of MOVISUITE® V2.40 for MOVI-C® CONTROLLER and MOVI-C® FIELD CONTROLLER with firmware V08.00 or later, protect against exploiting these vulnerabilities. Also observe the chapter "General corrective measures".</p> |
| M12 | <p>Observe chapter "General corrective measures".</p> |
| M13 | <p>To exploit this vulnerability, the project, project archive or library file must be opened outside of MOVISUITE® or via the standard CODESYS.</p> <p>MOVISUITE® is not affected by the vulnerability because the affected CODESYS plug-in is not used in the MOVISUITE® IEC Editor. Installing MOVISUITE® standard installs a standard CODESYS with a corresponding link for opening project, project archive and library files by double-clicking.</p> <p>Steps for rectification:</p> <ul style="list-style-type: none"> • Install CODESYS V3.5 SP19 Patch 2 or later. • Do not use CODESYS V3.5 SP18 Patch 2 anymore. • CODESYS V3.5 SP18 Patch 2 must still be installed for MOVISUITE® to function correctly. |
| M14 | <p>If you are working exclusively with MOVISUITE® and code generation: MOVISUITE® generates codesys projects that connect to the MOVI-C® CONTROLLER and MOVI-C® FIELD CONTROLLER via IP addresses. Thus, the node name is irrelevant.</p> <p>The general case of the connection to the controller via the CODESYS IEC Editor as stand-alone is still being processed. To exploit this vulnerability, a successful login must take place on the affected product. User management with strong passwords and secure engineering, which are available as of MOVISUITE® V2.40 for MOVI-C® CONTROLLER and MOVI-C® FIELD CONTROLLER with firmware V08.00 or later, protect against exploiting these vulnerabilities. If the node name has been changed, you can still connect to the controller via the device address or the IP address. After successful authentication, you can set the node name back to the original value.</p> |
| M15 | <p>Currently under review.</p> <p>You can fix the vulnerability manually by updating the CODESYS scripting to version 4.1.0.0 or later using the CODESYS installer. You can find the package on the CODESYS download page.</p> |
| M16 | <p>Currently under review.</p> <p>You can fix the vulnerability manually by downloading and installing the WIBU CodeMeter User Runtime for Windows version V7.60c or later from the company's page. By default, CodeMeter is not configured as a network server if it is installed via MOVISUITE® or the IEC Editor.</p> |

As of: Sep 19, 2023

4.2 Mobile assistance systems with VDA5050 interface

The vulnerabilities listed in chapters "Security vulnerabilities in CODESYS products" (→ 4) and "Affected products" (→ 6) affect the motion controller and the central data transfer controller in the AGV. Both controllers only have to be accessible for engineering access via WLAN and the WLAN client of the assistance system. For the vehicle controller itself, the AGV independently establishes a connection to the stationary MQTT broker via the WLAN client; incoming connections via NATP are not

4 Product-specific information and measures

Mobile assistance systems with VDA5050 interface

required in normal operation. SEW-EURODRIVE therefore recommends deactivating the entered NATP connections in the WLAN client at least to the two above-mentioned controllers after completion of the engineering work according to the following screenshot.

SIEMENS

IP Network Address Port Translation (NAPT)

Basic NATP

Interface: P1
Traffic Type: TCP
Global Port: 8080
Local IP Address:
Local Port: 8080

| Select | Enable | Interface | Traffic Type | Global Port | Local IP Address | Local Port |
|--------------------------|-------------------------------------|-----------|--------------|-------------|------------------|------------|
| <input type="checkbox"/> | <input type="checkbox"/> | P1 | TCP | 8080 | 192.168.24.20 | 8080 |
| <input type="checkbox"/> | <input type="checkbox"/> | P1 | TCP | 3390 | 192.168.24.20 | 3389 |
| <input type="checkbox"/> | <input type="checkbox"/> | P1 | TCP | 1883 | 192.168.24.20 | 1883 |
| <input type="checkbox"/> | <input type="checkbox"/> | P1 | TCP | 11740 | 192.168.24.21 | 11740 |
| <input type="checkbox"/> | <input type="checkbox"/> | P1 | TCP | 310 | 192.168.24.21 | 310 |
| <input type="checkbox"/> | <input type="checkbox"/> | P1 | TCP | 21 | 192.168.24.21 | 21 |
| <input type="checkbox"/> | <input type="checkbox"/> | P1 | UDP | 8000 | 192.168.24.50 | 8000 |
| <input type="checkbox"/> | <input type="checkbox"/> | P1 | TCP | 10022 | 192.168.24.60 | 22 |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | P1 | TCP | 1080 | 192.168.24.60 | 1080 |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | P1 | TCP | 8081 | 192.168.24.60 | 8081 |

10 entries.

Create Delete Set Values Refresh

9007242587830667

This ensures that the existing weak points cannot be exploited via the (WLAN) network during normal operation of the vehicles. If engineering activities are required, individually required NATP releases can easily be temporarily activated via the web interface in the WLAN client. Since all affected mobile assistance systems are intended for operation in production or assembly halls with limited access, an accidental or even malicious connection to the AGV's LAN connection for downloading malicious software into the vehicles that exploits given weak points is unlikely.

As of: Sep 19, 2023

5 General information

5.1 Disclaimer

This document is intended solely to provide information to our customers. The contents have been created with the greatest care, and efforts are made to ensure that they are as up to date as possible. However, SEW-EURODRIVE accepts no liability for the information provided being correct, complete, or up to date. It is published without recognition of any legal obligation.

The proposed corrective measures are for general informational purposes. Whether or to what extent these are applicable to your application environment is subject to your review of the specific conditions on site.

5.2 Product names and trademarks

The product names mentioned in this documentation are trademarks or registered trademarks of the respective titleholders.

5.3 Copyright notice

© 2023 SEW-EURODRIVE. All rights reserved. Copyright law prohibits the unauthorized reproduction, modification, distribution and use of this document – in whole or in part.

5.4 Document history

This customer information is continually updated as new information becomes available, and the most recent version can be found at www.sew.eurodrive.de.

| Version | Date of publication | Changes |
|---------|---------------------|------------------|
| 1 | September 19, 2023 | Initial document |







SEW-EURODRIVE
Driving the world

SEW
EURODRIVE

SEW-EURODRIVE GmbH & Co KG
Ernst-Blickle-Str. 42
76646 BRUCHSAL
GERMANY
Tel. +49 7251 75-0
Fax +49 7251 75-1970
sew@sew-eurodrive.com
→ www.sew-eurodrive.com