



MOVISUITE® ProjectFixer V1.1.0.0
for MOVISUITE® V2.2.12.0



MOVI-C®

Date: 16. June 2020
Version: 002

Problem description:

Installing a Windows 10 patch \geq 1809 has the effect that the MOVISUITE® projects are no longer displayed in MOVISUITE V2.2.

This behavior was first noticed with the Windows 10 patch 1809, but further Windows 10 patches followed where the MOVISUITE® ProjectFixer can be used without modification.

Reason:

The reason for the necessary update of the MOVISUITE® projects is a Windows-internal conversion of the Microsoft Compact database after installing a Windows 10 patch \geq 1809.

Solution:

The MOVISUITE® Project Fixer will make a backup copy of MOVISUITE projects. All MOVISUITE® projects will be opened one by one and then saved again. The projects are then visible again in MOVISUITE® V2.2 and can be opened. It does not matter if a ModuleUpdatePackage is installed.

Execution:

Unpack the ZIP file "SEW_MOVISUITE_V2.2_ProjectFixer_V1.1.0.zip" on the affected PC and then execute the file "ProjectFix.exe".

The execution time depends on the number of existing MOVISUITE® projects.

Information:

You require no administrator rights for the execution.

Version overview of MOVISUITE® ProjectFixer for MOVISUITE® V2.2.12.0:

Version	Date of publication	Implemented changes
V1.0.0.0	13.02.2020	First Version
V1.1.0.0	16.06.2020	<ul style="list-style-type: none">• Text changes, because not only the Windows 10 Patch 1809 is affected.• If the MOVISUITE® Project Fixer is used a second time, no error message is displayed (reason: backup folder already exists).